



☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

Pro R&K

Crate 2

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

p1/2

11151	3/210	(Flex Joint) (457mm)
11151	3/211	(Flex Joint) (305mm)
21121	10/1650	( $\frac{3}{4}$ X $1\frac{7}{8}$ w/ Nut & washer) (Q:18)
21121	10/1770	( $\frac{7}{8}$ X $3\frac{1}{2}$ bolt w/ nuts & washer (Q:8)
21121	20/1210	( $\frac{3}{4}$ X 2 bolt w/ Nut & washer Q:16)
21121	20/12090	( $\frac{5}{8}$ X $3\frac{1}{4}$ w/ Nut & washer Q:4)
21121	40/1280	( $\frac{3}{4}$ X $1\frac{7}{8}$ w/ Nut & washer Q:4)
21121	50/1130	( $\frac{3}{8}$ X 1 w/ Nut & washer Q:4)
21121	50/1140	( $\frac{3}{8}$ X $1\frac{1}{2}$ w/ Nuts & washer zinc coated Q:10)
21121	60/2070	( $\frac{3}{4}$ X $2\frac{1}{2}$ w/ nuts & washer Q:4)
21121	<del>60/2080</del>	( $\frac{3}{4}$ X 2 w/ nuts & washer Q:4)
21147	10/180	( $1\frac{1}{4}$ X 3 w/ Nut & washer Q:96)
21147	10/190	( $1\frac{1}{4}$ X 3 w/ Nut & washer Q:24)
21147	20/40	( $1\frac{1}{4}$ X 3 w/ Nut & washer zinc coated Q:24)
21147	20/70	(4" 150 graffiti) (Q:1)
21148	10/70	( $1\frac{1}{8}$ X $2\frac{3}{4}$ w/ Nuts & washer Q:20)
21148	10/80	( $\frac{3}{8}$ X $2\frac{1}{4}$ w/ Nut & washer Q:12)
21148	10/120	( $1\frac{1}{8}$ X $2\frac{3}{4}$ w/ Nut & washer Q:20)
21148	20/70	( $1\frac{1}{8}$ X $2\frac{3}{4}$ w/ Nut & washer Q:20)
21148	20/80	( $\frac{3}{8}$ X $2\frac{1}{4}$ w/ Nut & washer Q:12)
21148	20/120	( $1\frac{1}{8}$ X $2\frac{3}{4}$ w/ Nuts & washer Q:20)
21148	30/40	( $1\frac{1}{4}$ X 3 w/ Nut & washer Q:72)
21148	60/10	( $\frac{1}{2}$ X $1\frac{1}{4}$ w/ Nut & washer Q:16)
21148	60/20	( $\frac{3}{8}$ X $1\frac{1}{4}$ w/ Nut & washer Q:40)
21148	60/30	( $\frac{3}{8}$ flat washers Q:80)
21148	60/40	( $\frac{3}{8}$ X $1\frac{1}{4}$ bolt w/ Nuts & washer Q:16)
21151	220/40	(Garlock gasket 194 OD X 143 ID) (3M)
21151	270/91	(Garlock gasket 194 OD X 143 ID 3M) (Q:2)
21151	280/40	(Garlock gasket 194 OD X 143 ID 3M) (Q:2)
21151	330/101	(Garlock gasket 194 OD X 143 ID 3M) (Q:2)
21151	340/51	(3" 150 SPUD) (Q:2)
21161	20/30	(LG-1561 Flat glass level gauge)
21161	20/80	(LG-1561 Gauge Case for level gauge)
21161	20/80	(Flex hose) (2" 305mm)



**IPAC**  
SERVICES CORP.

☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

Pm-P&K

Crate 2

p2/a

21161	90/30	( 4" ISO wafer check )	
11121	20/2060	( 5/8 x 2 CW / Nut & washer )	Q : 8
11121	40/1290	( 5/8 x 2 CW / Nut & washer )	Q : 16
11147	20/61	( Plate Flange )	RF-4-A